


# STATION 5

## Morrison Road Bridge over the Contoocook River

Option B—Identified by Hoyle, Tanner & Associates, Inc.



### DETAILS

- 1) Advisory shoulder for cyclists and pedestrians, to be directed over a foot-bridge
- A true, protected bike lane is not possible due to the limited width of roadway
  - Full sidewalk is not possible due to expensive cost to install and maintain

2) Pavement markings

- 3) Foot bridge added for pedestrian and cyclists to cross over river. Bridge deck widened enough for two-lane car travel but not enough for an advisory shoulder.

