


STATION 6

Grove Street Extension



DETAILS

1) Advisory shoulder for cyclists and pedestrians

- A true, protected bike lane is not possible due to the limited width of roadway
- Full sidewalk is not possible due to expensive cost to install and maintain

2) Pavement markings

3) Crosswalk connection to Common Pathway

